




HOW TO MAKE PRESSED FLOWER STAINED GLASS



1



SELECT PATTERNS

For colored glass: Place the clear glass on top.

ARRANGE FLOWERS

- Use tweezers to arrange flower designs on the **back** glass piece.


Avoid:

- stacking too many flowers on top of each other.
- Placing flowers close to edges.

2



3



COPPER FOIL

- Add copper foil as 1 long strip onto the sides and edges.
- Take your time making the one long foil strip be even.
- Use scissors to cut when done.


4



ADD TOP GLASS

- Be gentle because the flower designs might slightly move.
- Gently place the top glass onto the back glass piece. (Note: colored glass in back).

5



USE CLAMPS

Use at least 3 clamps to secure the flower designs.

6



COPPER FOIL

- Slowly tape the two pieces together.
- When you need to move a clamp - Add one before taking one-off.


GLOVE AND FLUX

- 1 glove on the hand you'll use to pick up the glass.
- 1 small cup of flux and 1 paintbrush.
- Gently brush a small amount of flux onto the copper. No need to drench and avoid puddles of flux.

7



8




SOLDERING TIME!

- Tap the solderer onto the solder metal.
- Rub the solderer across the copper.
- Cover each corner then flip and do sides last.
- **BEWARE:** the glass will get hot.

JUMP RING

- Use pliers to slightly open the ring.
- Place 1 sheet of glass above the glass.
- Place the jump ring onto the sheet.
- Apply flux and solder the ring onto the stained glass

9



10



CLEAN AND PATINA

- Spray a small amount of cleaner and wipe copper off.
- Feel free to select either black or copper patina or leave it as silver.
- Grab a cup of patina and a Q-tip.
- Gently rub the Q- tip on the solder.
- Wipe the solder off with water and towel.